

No. 9046

COOL-LITE TESTER

Used for candling eggs.

Instructions

Hold light up to the large end of the egg in a dark room. Use to check progress of development. After 10 days check for infertility (entire egg will glow). Remove infertile eggs from the incubator to provide more room. Two to Three days before the projected hatch date approximately $\frac{1}{3}$ of the egg should show an air pocket as indicated in the photo.



Manufactured by G.Q.F. Mfg Co., P.O. Box 1552, Savannah, GA. 31402